


San Francisco State University

- Access symbol key**
- M Accessible men's restroom
 - W Accessible women's restroom
 - U Accessible unisex restroom
(nonaccessible restrooms not shown)
 - 4/4/4 Floor numbers (only listed if limited)
 - ☎ TTY phone (6)
 - ☎ Videophone booth (1)
 - ⬆ Elevator(s) (floors shown if limited)
 - ▶ Accessible entrance
 - ▶ Accessible entrance with power door
 - P Accessible Parking (#'s indicate floors)

Location key

Administration (ADM)	H7	Library (LIB)	H6
Bookstore	G6	Little Theatre (CA)	H5
Burk Hall (BH)	G4-5	Mail Services	D4
Business (BUS)	G7/H7	Mary Park Hall	E1/F1
C. Chavez Student Center.....	G5-6/H5	Mary Ward Hall	F1-2
Car Rental/Lot 25	B3	McKenna Theatre	H4/H4
Child Care Center	E1/F2	Memorial Grove	G6
Comm. Involvement Cent. (CIC)	G6	Parking Garage	E3-4
Conference Center	F3	Parking & Transportation	D3
Coppola Theatre (FA)	H5	Physical Therapy	G6
Corporation Yard	C3/D3	Public Safety (Campus Police)	D3
Creative Arts (CA)	H4-5	Recycling	E4
Dining Center	F2	Science (SCI)	F7-8/G7-8
Ethnic Studies & Psychology (EP)	F5	Seven Hills Center	F2
Facilities	D3	Shipping & Receiving	D4
Fine Arts (FA)	G4-5/H4-5	Softball Field	H1
Garden of Remembrance	G5	Student Housing Office	F2
Gymnasium (GYM)	F5-6	Student Services/OneStop Cen. (SSB) ..	F4
Health Center (SHS)	F4-5	Studio Theatre (CA)	H5
Hensill Hall (HH)	F7-8	Sutro Library	A4/B4
HSS	G7-8/H7-8	Temporary Buildings	E7/F7
Humanities (HUM)	G3-4/H3-4	Thornton Hall (TH)	E7/F7
Jack Adams Hall (SC)	G5-6	The Towers	F2-3
Knuth Hall (CA)	H4-5	University Park North	
Labor Archives	A4-5/B4	University Park South	H1-4/I1-7
Lakeview Center (LVC)	C2/C3	Village at Centennial Square ...	F3/G2-3



- Symbol key**
- 18 Public Transit
 - S BART Shuttle Stops
 - \$ ATM Machines
 - 20 Parking Lots
 - P Metered Parking
 - E Emergency Phone
 - S Smoking Area
 - E Authorized Route To/From Bike Barn

- Access path key***
- Accessible Route—This path generally conforms to accessibility standards.
 - Areas that may be a travel hazard (where the slope exceeds the standard maximum ramp slope [8.3%], or the cross-slope is significant [exceeds 4%]).
 - Ramp (5%–8.3%)—Complying ramp along the accessible route.
 - Partially Accessible Route—This path generally conforms to accessibility standards, but there may be excessive cross-slope (over 2%) or other irregularities in a portion of the path, often along the path edge. There is usually a 48" wide complying path along these routes, though it may not be a straight or direct line.
 - Lighter shade indicates path continues underneath overhang.

*Note: The map and information on pathways are limited by the scale. The accessible route should be clear to a person at a location, while the dashed line is intended to indicate where keener observation may be necessary to locate the accessible route. Pathways are generally asphalt and subject to weathering, erosion, uplifting, and other changes that may create navigational issues. SFSU is committed to maintaining the accessible route. Please report any irregularities to Disability Programs and Resource Center, 415-338-2472 (voice, TTY).